DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-006149 Address: 333 Burma Road **Date Inspected:** 09-Apr-2009

City: Oakland, CA 94607

OSM Arrival Time: 645 **Project Name:** SAS Superstructure **OSM Departure Time:** 1845 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Shi Lei **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component: OBG** Segments

Summary of Items Observed:

On this date CALTRANS OSM Quality Assurance (QA) Inspector Dan Hernandez was present during the times noted above for observations relative to the work being performed.

This QA Inspector observed the following work in progress:

Bay 2 OBG Assembly

Segment 1AE

Flux Cored Arc Welding (FCAW) of weld joint SSD34-PP8.5-370 located on lifting lug at Panel Point 8.5. Welder is identified as 045240. ZPMC QC is identified as Geng Wei. The welding variables recorded by QC appeared to comply with the Applicable WPS.

Shielded Metal Arc Welding (SMAW) of weld joint SEG004-034 located on Deck Panel Splice. Welder is identified as 069896. ZPMC QC is identified as Geng Wei. The welding variables recorded by QC appeared to comply with the Applicable WPS.

Segment 1AE

Flux Cored Arc Welding (FCAW) of weld joint SSD35A-PP90-003, 004 located on FB884. Welder is identified as 045240. ZPMC QC is identified as Geng Wei. The welding variables recorded by QC appeared to comply with

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

the Applicable WPS.

Flux Cored Arc Welding (FCAW) of weld joint SSD36-PP9.5-003, 004 located on FB85A. Welder is identified as 067949. ZPMC QC is identified as Geng Wei. The welding variables recorded by QC appeared to comply with the Applicable WPS.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Hernandez,Dan	Quality Assurance Inspector
Reviewed By:	Carreon, Albert	QA Reviewer